

# Existing Bus Garage Current Conditions



*Bus Garage North Elevation*



*The 1940's building on South Street*



*Tool Storage Area*



*Structural Crack at Corner*



*Antiquated Lift*



*Concrete Lintel*



*Distance Between Buses and Over-head Door*



*Column & Roof Drain*



# NEW TRANSPORTATION FACILITY PROJECT Geneseo Central School District